

VACUUM GAUGE AND MANOMETERS



- ▶ Analogue indicator, springjoint – lever system
- ▶ The instruments include nut for installation on a panel

TECHNICAL DATA

Description	Unit	Value
Accuracy, of full scale	%	2.5
Material		CuZn, ABS, PMMA

TECHNICAL DATA, SPECIFIC

Description	Unit	Value		
		3101602	3101603	3101626
Weight	g	90	55	50
Signal range	MPa	0–0.1	0–1	0–0.25
Medium		Vacuum	Over pressure	

ORDERING INFORMATION

	Description	Art. No.
B	Vacuum gauge 100 -kPa, with nut	3101602
A	Manometer 1 MPa	3101603
A	Manometer 250 kPa	3101626

